

ARICAS

GEARED HEAD MILLING & DRILLING MACHING


OPERATION MANUAL AND PARTS LIST

MODEL :

GEM-400G	
GEM-400GD	
GEM-400GS	
GEM-400GCT	✓
GEM-450G	
GEM-500G II	
GEM-500G III	

CONTENT

1.ELECTRICAL CIRCUITING DIAGRAM	P1
2.BEFORE OPERATION	P2
3.AFTER OPERATION	P2
4.ADJUSTMENT OF HEAD	P2
5.REPARING DRILLING	P2
6.LIFTING	P3
7.CLEANING & LUBRICATING	P4
8.USE OF MAIN MACHINE PARTS	P4
9.PRECAUTION FOR OPERATION	P4
10.PREPARING MILLING	P5
11.ADJUSTING TABLE SLACK	P5
12.CLAMPING, TABLE BASE, AND MACHINE BASE	P5
13.SPEED CHANGING	P6
14.SPINDLE SPEEDS R.P.M.	P6
15.EXTRA TOOLING AND ACCESSORIES	P6
16.TAPPING EQUIPMENT	P7
17.TROUBLE SHOOTING	P7
18.DRAWING, PARTS LIST	P8~P12
19.ELETRICAL CONTROL PART LIST	P13



2. BEFORE OPERATION:

- (a) FILL THE LUBRICANT.
- (b) IN ORDER TO KEEP THE ACCURATE PRECISION, THE TABLE MUST BE FREE FROM DUST AND OIL DEPOSITS.
- (c) MAKE SURE THAT THE TOOLS ARE CORRECTLY SET AND THE WORKPIECE IS SET FIRMLY.
- (d) MAKE SURE THAT THE SPEED IS NOT SET TOO FAST.
- (e) MAKE SURE THAT EVERYTHING IS READY BEFORE USE.

3. AFTER OPERATION:

- (a) TURN OFF THE ELECTRICAL SWITCH.
- (b) TAKE OFF THE TOOLS.
- (c) CLEAN THE MACHINE AND LUBRICATED WITH LUBRICANT.

4. ADJUSTMENT OF HEAD:

- (a) TO RAISE AND LOWER THE HEAD, LOSEN THE TWO BOLTS SHOWN IN FIG.2. USE THE LEFT SIDE HEAD HANDLE TO RAISE AND LOWER THE HEAD ON ITS RACK AND PINION MECHANISM. WHEN THE DESIRED HEIGHT IS REACHED, TIGHTEN THE BOLTS TO AVOID VIBRATION.
- (b) HEAD MAY BE ROTATED 90° BY LOSENING THE SAME BOLTS MENTIONED ABOVE. ADJUST THE HEAD TO THE DESIRED ANGLE, THEN FIX THE BOLT ACCORDING TO THE PROCESSING REQUIREMENT AND TIGHTEN TWO BOLTS AT THE SAME TIME TO FIX THE HEAD IF DRILLING & MILLING TOO MUCH.
- (c) UNSCREW 3 NUTS WHILE THE WORKPIECE NEEDS TO BE BEVEL DRILLED. TURN TO THE DEGREES AS THE PROCESSING REQUIREMENT, THEN LOCK THE 3 NUTS.





FIG 1

5. PREPARING DRILLING:

- (a) MAKE THE FEED HANDLE AND THE WORM INNER GEAR UNCLUTCHING BY MOVING FEED HANDLE, THEN STOP DOWN FEED.

6.LIFTING:



USE THE FOLLOWING FACILITIES TO LIFT THE MACHINE:

1.CRANE HOISTING.

2.2 PCS OF CABLES, EACH AT ϕ 12.7MM($\frac{1}{2}$ ") \times 1830MM(72")LONG.



3.1 STEEL BAR.

NOTE:1.MACHINE MUST ALWAYS BE KEPT BALANCED DURING LIFTING.

2.PLACE PROTECTING MATERIAL, SUCH AS HARD PAPER BOARD ,WOODEN WEDGES, ON ANY PART OF MACHINE THAT MIGHT BE CONTACTED BY THE CABLES.

3.CABLES MUST BE PLACED FIRMLY AT BOTH ENDS OF THE STEEL BARS TO PREVENT THE WIRES FROM SLIPPING OFF.

INSTALLATION :



USE THE FOLLOWING FACILITIES TO LIFT THE MACHINE:

1. CHAIN HOIST
2. CHAINS
3. 2PCS OF STEEL BARS EACH AT 25mm x 750mm LONG FOR FX-389D
4. 4PCS OF RING SCREWS EACH AT 8mm x 25mm LONG FOR FX-388D & FX-388C (PLEASE FIND FX-388D B-PART-NO72 & FX-388C B-PART- NO- 52)

NOTE : 1.MACHINE MUST ALWAYS BE KEPT BALANCED DURING LIFTING

2.PLACE PROTECTING MATERIAL, SUCH AS HARD PAPER BOARD, WOODEN WEDGES, ON ANY PART OF MACHINE THAT MIGHT BE CONTACTED BY THE CABLES

3.CABLES MUST BE PLACED FIRMLY AT BOTH ENDS OF THE STEEL BARS TO PREVENT THE WIRES FROM SLIPPING OFF

7. CLEANING & LUBRICATING:

- (1) THE MACHINE HAS BEEN COATED WITH A HEAVY GREASE TO PROTECT IT IN SHIPPING. THIS COATING SHOULD BE COMPLETELY REMOVED BEFORE OPERATING THE MACHINE. COMMERCIAL DEGREASER, KEROSENE OR SIMILAR SOLVENT MAY BE USED TO REMOVE THE GREASE FROM THE MACHINE, BUT AVOID GETTING SOLVENT ON BELTS OR OTHER RUBBER PARTS.
- (2) AFTER CLEANING, COAT ALL BRIGHT WORK WITH A LIGHT LUBRICANT. LUBRICATED ALL POINTS AS FIG.2.
- (3) LUBRICATING POINTS AS ARROWS INDICATED.




FIG 2

8. USE OF MAIN MACHINE PARTS (SEE FIG.2)

- (1) TO RAISE AND LOWER THE HEAD BY HEAD HANDLE.
- (2) EQUIPPED WITH AN ELECTRIC SWITCH.
- (3) TO ADJUST THE QUICK OR SLOW FEEDING BY FEED HANDLE.
- (4) TO ADJUST THE TABLE LEFT AND RIGHT TRAVEL BY TABLE HANDLE.
- (5) TO ADJUST THE TABLE FORE AND AFT TRAVEL BY TABLE HANDLE WHEEL.
- (6) TO OPERATE THE SPINDLE HANDLE WHEEL FOR MICRO FEED.
- (7) TO ADJUST THE SCALE SIZE ACCORDING TO WORKING NEED.
- (8) HIGH AND LOW SPEED LEVER.
- (9) 1,2,3 SPEED LEVER.
- (10) ELECTRICAL CONTROL BOX.

9. PRECAUTION FOR OPERATION

INSPECTING ALL PARTS FOR PROPER CONDITION BEFORE OPERATION, IF NORMAL SAFETY PRECAUTIONS ARE NOTICED CAREFULLY, THIS MACHINE CAN PROVIDE THE OPERATION OF ACCURATE SERVICE.

CLEANING & LUBRICATING:

- (1) THE MACHINE HAS BEEN COATED WITH A HEAVY GREASE TO PROTECT IT IN SHIPPING. THIS COATING SHOULD BE COMPLETELY REMOVED BEFORE OPERATING THE MACHINE. COMMERCIAL DEGREASER, KEROSENE OR SIMILAR SOLVENT MAY BE USED TO REMOVE THE GREASE FROM THE MACHINE, BUT AVOID GETTING SOLVENT ON BELTS OR OTHER RUBBER PARTS.
- (2) AFTER CLEANING, COAT ALL BRIGHT WORK WITH A LIGHT LUBRICANT. LUBRICATED ALL POINTS AS FIG.2.
- (3) LUBRICATING POINTS AS ARROWS INDICATED.




FIG 2

USE OF MAIN MACHINE PARTS (SEE FIG.2)

- (1) TO RAISE AND LOWER THE HEAD BY HEAD HANDLE.
- (2) EQUIPPED WITH AN ELECTRIC SWITCH.
- (3) TO ADJUST THE QUICK OR SLOW FEEDING BY FEED HANDLE.
- (4) TO ADJUST THE TABLE LEFT AND RIGHT TRAVEL BY TABLE HANDLE.
- (5) TO ADJUST THE TABLE FORE AND AFT TRAVEL BY TABLE HANDLE WHEEL.
- (6) TO OPERATE THE SPINDLE HANDLE WHEEL FOR MICRO FEED.
- (7) TO ADJUST THE SCALE SIZE ACCORDING TO WORKING NEED.
- (8) HIGH AND LOW SPEED LEVER.
- (9) 1,2,3 SPEED LEVER.
- (10) ELECTRICAL CONTROL BOX.

PRECAUTION FOR OPERATION

INSPECTING ALL PARTS FOR PROPER CONDITION BEFORE OPERATION, IF NORMAL SAFETY PRECAUTIONS ARE NOTICED CAREFULLY, THIS MACHINE CAN PROVIDE THE OPERATION OF ACCURATE SERVICE.

10. PREPARING MILLING:

- (a) ADJUST SCREW ON THE GRADUATED DIAL TO THE DESIRED HIGHEST POSITION.
- (b) MAKE THE FEED HANDLE AND THE WORM INNER GEAR CLUTCHING BY MOVING THE FEED HANDLE, THEN PERFORM MILLING BY MICRO FEED.
- (c) ADJUST SPINDLE TO THE DESIRED WORKING POSITION BY SPINDLE HANDWHEEL AND LOCK THE RACK GEAR SLEEVE AT THE DESIRED HEIGHT WITH FIXED BOLT.

11. ADJUSTING TABLE SLACK:

- (1) YOUR MARK IV IS EQUIPPED WITH FULL LENGTH TAPERED SLIDING PLATE TO ADJUST FOR EXCESS SLACK IN FORE AND AFT. LEFT AND RIGHT TABLE TRAVEL.
- (2) TIGHTEN THE SLIDING PLATE BOLT CLOCKWISE WITH A BIG SCREW DRIVER FOR EXCESS SLACK.
- (3) RELEASE THE SLIDING PLATE BOLT A LITTLE COUNTER-CLOCKWISE IF TOO TIGHT.
- (4) TO ADJUST LEFT AND RIGHT TRAVEL, ADJUST THE SLIDING PLATE BOLT UNTIL FEEL A SLIGHT DRAG WHEN TURNING THE TABLE (FIG.3).
- (5) TO ADJUST FORE AND AFT TRAVEL, ADJUST THE SLIDING PLATE BOLT AS SHOWN IN FIG.3.





FIG 3



12. CLAMPING, TABLE BASE, AND MACHINE BASE:

- (1) WHEN MILLING LEFT AND RIGHT, IT IS ADVISABLE TO LOCK THE FORE AND AFT TABLE TRAVEL TO INSURE THE ACCURACY OF YOUR WORK. TO DO THIS, TIGHTEN THE SMALL LEAF SCREW LOCATED ON THE RIGHT SIDE OF THE TABLE BASE (FIG.4)
- (2) TO TIGHTEN THE LEFT AND RIGHT TRAVEL OF THE TABLE FOR FORE AND AFT MILLING, TIGHTEN THE TWO SMALL LEAF SCREW ON THE FRONT OF THE TABLE BASE (FIG.4).
- (3) ADJUSTABLE TRAVEL STOPS ARE PROVIDED ON THE FRONT OF THE TABLE FOR CONTROL OF CROSS TRAVEL AND THE DESIRED MILLING LENGTH.






FIG 4

13.SPEED CHANGING:



ATTENTION
DO NOT CHANGE SPINDLE
SPEED LEVERS WHEN THE
SPINDLE IS ROTATING

- 1.TURN POWER OFF.
- 2.FIG 1-8 (H.L.)LEVERS.
- 3.FIG 1-9 (1,2,3,SPEED) LEVERES.

14.SPINDLE SPEEDS R.P.M.

LEVERS	50HZ	60HZ	2P/4P	2P/4P
H1	1250	1500	2500	3000
H2	670	800	1240	1600
H3	380	450	760	900
L1	190	230	380	460
L2	110	130	220	260
L3	50	60	100	120

15.EXTRA TOOLING AND ACCESSORIES

EACH OF ~~MACHINE~~ IS EQUIPPED WITH A MT #3 SPINDLE TAPER OR A R-8 SPINDLE TAPER (EXAMPLES BELOW). CONTACT YOUR LOCAL DISTRIBUTOR OR A MAJOR CUTTING TOOL DISTRIBUTOR TO OBTAIN ANY OF THESE ACCESSORIES:

TAPER DRILLS

REAMERS

END MILLS

CUTTER ARBOR

TAPS


COLLETS

ADAPTERS AND SLEEVES

NI-30#

16. TAPPING EQUIPMENT:

THIS MACHINE CAN BE EQUIPPED WITH AN ELECTRIC SWITCH FOR TAPPING OPERATION CLOCKWISE OR COUNTERCLOCKWISE, AND THE WORKING DEPTH ALSO CAN BE ADJUSTED BY THE LIMIT SWITCH. (ELECTRIC SWITCH WILL BE INSTALLED ACCORDING TO YOUR REQUIREMENT, AND YOU ARE JUST PAY THE COST ONLY.)



SPECIFICATION OF T-SLOT
THE SIZE OF T-SLOT ON TABLE AS FIG.5:

17. TROUBLE SHOOTING:

(1) SPINDLE

- 1) WHEN YOU FIND THE SPINDLE LOOSE, PLEASE TAKE OFF THE NAME PLATE, THE TWO SPINDLE NUTS CAN BE ADJUSTED IN POSITION.
- 2) WHEN SPINDLE IS LOOSE AFTER YOU PULL IT DOWN AND CAN NOT BE RETURNED OR CAN NOT BE OPERATED, EACH OTHER YOU MAY:
 - A. CHECK THE SPRING IN THE SPRING COVER IS BROKEN OR NOT. IF YES, REPLACE A NEW SPRING.
 - B. CHECK IN THE GEAR RACK THAT PREVENT THE MOVING. IF YES, BRUSH UP THE CHIPS, THEN USE OIL STONE GRIND THE RACK GEAR TO MAKE IT SMOOTH.

(2) GEAR-BOX

- 1) THERE IS A HOLE ON THE GEAR COVER FOR ADDING THE OIL, ALSO ANOTHER HOLE UNDER THE GEAR BOX FOR USED OIL.
- 2) ALWAYS LET GEAR BOX OIL PROTECT. DON'T LET IT OVER LEVEL H. DON'T LET IT BELOW L.
- 3) GEAR OIL: ULTRALUBE OIL 90#.

(3) GEAR

WHEN START THE WORKING, NEVER CHANGE THE SPEEDS, BECAUSE IT WILL DAMAGED THE MACHINE.

A. SERIOUSLY

- 1) GEAR WILL BE BROKEN (REPLACE A NEW ONE)
- 2) GEAR LEVER WILL BE BROKEN (REPLACE A NEW ONE)
- 3) THE MACHINE CAN NOT BE OPERATED.

B. SLIGHTLY


- 1) GEAR WILL BE DEFORMED.
- 2) NOISE WILL BE GENERATED FROM THE GEAR.

(4) SPINDLE DEFORMED

REASONS: USE WRONG CLAMPS WHEN MACHINEING A BIG WORKPIECE. THIS WILL CAUSE THE WORKPIECE VISIBLY MOVED BACK AND FORTH THEN


METHOD: REPLACE IT.

H-PART




1	OIL SEAL(TCØ45xØ72x10T)	1	35A	CAP SCREW (M6x14L)	1
2	SPINDLE (MT3 OR R8)	1	36	WORM SHAFT	1
3	TAPPER ROLLOR(#30207)	1	36A	SET SCREW (M6x8L)	4
4	QUILL	1	36B	KEY (4x4x20L)	4
5	TAPPER ROLLOR (#30206)	1	37	THRUST BEARING (#51102)	2
6	CAP SCREW (M8x30L)	1	38	WASHER	1
7	GEAR WASHER	1	38A	GRIP (3/8")	1
7A	SPINLE NUT	1	39	SLEEVE	1
8	BRACKET	2	40	MICRO FEED GRADUATED DIAL(MM/INCH)	1
9	O RING 75Ø	1	41	SET SCREW (M6x8L)	1
10	HEX NUT	1	42	MICRO FEED HANDLE	1
11	STROKE ROD	1	43	OIL PLUG (3/8"~PT)	2
12	CAP SCREW(M8x16L)	1	44	GEAR CHANGE SPEED 1,2,3 ROD	1
13	FIXING BLOCK	1	45	OIL SEAL (TCØ22xØ12x7T)	2
14	NAME PLATE	1	46	SPRING SPIN (4Øx40L)	2
15	PAN SCREW	4	47	FIXING SEAT	2
16	CLAMPING PIPE	1	48	GEAR CHANGE SPEED LEVER	2
17	CLAMPING HANDLE	1	49	GRIP HANDLE(3/8")	2
18	CLAMPING NUT	1	50	GEAR CHANGE H&L ROD	1
19	GEAR BOX	1	51	SLEEVE	1
19A	OIL WINDOW(1/2" PT)	1	52	OIL SEAL (TCØ47x35x7T)	1
20	DISC SPRING SET	1	53	GEAR (M2x53T)	1
21	HEX NUT	1	54	BALL BEARING(6007Z)	2
22	PINION SHAFT	1	55	C-RING (S35)	1
23	KEY (5x5x40L)	1	56	SNAP RING(R62)	1
24	KEY (5x5x20L)	1	57	DRAW BAR (M12x1.75P)	1
25	C-RING(S26)	1	58	BALL BEARING (6202Z)	5
26	WORM GEAR	1	59	C-RING (S22)	1
27	INDICATOR	1	60	GEAR (M2x41T)	1
28	RIVET	2	61	C-SHAFT GEAR (M2x15T)	1
29	WORM GEAR COVER	1	62	SNAP-RING (R35)	2
30	CAP SCREW (M8x16L)	2	63	END COVER	2
31	MIRCO FEED CONNECTOR	1	64	GEAR ((M2x35T))	1
32	FIXING SEAT	1	65	GEAR (M2x28T)	1
33	FIXING SEAT HANDLE	3	66	GEAR (M2x44T)	1
34	GRIP HANDLE 1/2"	3	67	C-RING (S18)	2
35	CAP SCREW (3/8"x1")	1	68	B-SHAFT	1

68A	KEY (5x5x50L)	1
68B	KEY (6x6x75L)	1
69	GEAR (M2x16T/42T)	1
69A	SPRING	2
69B	BALL Ø8	2
70	GEAR (M2x31T/15T/23T)	1
71	A-SHAFT	1
72	GEAR BOX COVER	1
73	CAP SCREW(6x25L)	8
74	SPINDLE TOP COVER	1
75	TAPER PIN(NO.4)	2
76	MOTOR(AC 1.5HP/2 HP)	1
77	KEY(6x6x30L)	1



61	CROSS TRAVEL GIB	1
62	CROSS LEAD SCREW NUT	1
63	WING SCREW(3/8)	2
64	LONGITUDINAL TRAVEL GIB	1
65	CROSS LEAD SCREW	1
66	BEARING SEAT SET	1
67	MEMORY RING	3
68	HANDLE GRIP	3
69	CAP SCREW(M8x40L)	1
70	CAP SCREW(M8x12L)	3
71	MACHINE STAND	1


GEM-400G B-PART



B--PART


1	BASE	1
2	SPRING WASHER	4
3	HEX BOLT	4
4	FLANGE RING	1
5	TRAVEL GIB SCREW 5/16"-20UNF× 25L)	4
6	RACK GEAR	1
7	COLUMN	1
8	RUBBER CHIPSA COVER	1
9	CAP SCREW (M8× 16L)	4
10	SET SCREW (M8× 10L)	2
11	COVER SEAT	1
12	WASHER	4
13	WORKING TABLE	1
14	LONGITUDINAL TRAVEL GIB	1
15	CAP SCREW (M6× 16L)	2
16	STOPPER BUSH	2
17	STOPPER SET	2
18	WORM WHEEL	1
19	HANDLE SCREW	1
20	BEARING (#6002Z)	5
21	BEARING BASE	1
22	CAP SCREW (M5× 6L)	6
23	BALL BEARING (#6002Z)	5
24	SET SCREW (M5× 6L)	3
25	HANDWHEEL	3
26	TRAVEL DIAL	3
27	WASHER	3
28	CAP SCREW (M8× 12L)	3
29	GRIP	3
30	KEY (5× 5× 12L)	3
31	CROSS LEADSCREW NUT	1
32	CAP SCREW (M8× 20L)	2
33	CROSS TRAVEL GIB	1
34	SADDLE	1
35	WING SCREW (3/8")	2
36	STOPPER BLOCK	1
37	CAP SCREW (M8× 16L)	2
38	WING SCREW (M8)	2
39	LONGITUDINAL LEADSCREW NUT	1
40	CAP SCREW (M8× 30L)	1
41	BEARING SEAT SET	2
42	LONGITUDINAL LEADSCREW	1
43	RING NUT	4

GEM-400GS




BASE LIST

NO.	DESCRIPTION	Q'TY
1	BASE	1
2	SPRING WASHER	4
3	HEX BOLT 5/8" x 1/2" L	4
4	FLANGE RING	1
5	CLAMPING BOLT 1/2"	2
6	RACK GEAR	1
7	COLUMN (115mm)	1
8	CLAMPING RING	1
9	SET SCREW M10x12L	2
10	SET SCREW M8x10L	1
11	COVER SEAT	1
12	CLAMPING BOLT 1/2"	1
13	SQUARE TABLE	1
14	CRANK HANDLE GIP	1
15	SET SCREW M8x10L	1
16	CRANK HANDLE	1
17	WORM SHAFT	1
18	WORM WHEEL	1




B-PART

1	BASE	1	45	CAP SCREW (M6x16L)	2
2	SPRING WASHER	4	46	LONGITUDIAL TRAVEL GIB	1
3	HEX BOLT (5/8x3L)	4	47	WORKING TABLE	1
4	FLANGE RING	1	48	WASHER	4
5	CLAMPING BOLT(1/2)	2	49	CAP SCREW (M5x12L)	4
6	RACK GEAR	1	50	RUBBER CHIPS COVER	1
7	COLUMN (Ø115)	1	51	TRAVEL GIB SCREW 5/16"-20UNFx25L)	4
8	CLAMPING RING	1	52	RING NUT	4
9	SET SCREW (M8x12L)	3			
10	SET SCREW (M8x10L)	2			
11	COVER SEAT	1			
12	CLAMPING BOLT	1			
13	TABLE BASE	1			
14	CRANK HANDLE GIP	1			
15	SET SCREW (M8x10L)	1			
16	CRANK HANDLE	1			
17	WORM SHAFT	1			
18	WORM WHEEL	1			
19	HANDLE SCREW	1			
20	BEARING (#6002Z)	5			
21	BEARING BASE	1			
22	CAP SCREW (M6x16L)	6			
23	BALL BEARING (#6002Z)	5			
24	SET SCREW (M5x6L)	3			
25	HANDLE WHEEL	3			
26	TRAVEL DIAL	3			
27	WASHER	3			
28	CAP SCREW (M8x12L)	3			
29	GRIP	3			
30	KEY (5x5x12L)	3			
31	CROSS LEADSCREW NUT	1			
32	CAP SCREW (M8x20L)	2			
33	CROSS TRAVEL GIB	1			
34	SADDLE	1			
35	WING SCREW (3/8")	2			
36	STOPPER BLOCK	1			
37	CAP SCREW (M8x16L)	2			
38	WING SCREW (M8)	2			
39	LONGITUDIAL LEADSCREW NUT	1			
40	CAP SCREW (M8x30L)	1			
41	BEARING SEAT SET	2			
42	LONGITUDIAL LEADSCREW	2			
43	STOPPER SET	2			
44	STOPPER BUSH	2			




CENTRAL LUBRICATING OIL-FEEDING EQUIPMENT



ITEM NO.	PARTS NO.	DESCRIPTION
1	9001	Hand Oiler
2	9002	Aluminum Pipe
3	9003	Elbow Joint (8 Req.)
4	9004	T-Joint
5	9005	Straight Joint (7 Req.)
6	9006	Oil Regulating Distributor
7	9007	Outside Steel Flexible Tube

GEM-500G II



1	BASE	1	37	CAP SCREW (M8x16L)	4
2	SPRING WASHER(M16)	4	38	HANDLE	1
3	HEX BOLT(5/8"x2-1/2"L)	4	39	GRIP	1
4	MAIN COLUMN	1	40	CAP SCREW (M8x25L)	2
5	UP & DOWN TRAVEL GIB	1	40A	WASHER (M8)	4
6	GIB ADJUSTING SCREW(5/16"x24 UNF)	6	41	WASHER(M8)	3
7	UP & DOWN TRAVEL BASE	1	42	SET SCREW(M5x8L)	3
8	Z-AXIS LEAD SCREW NUT	1	43	HANDLE WREEL	3
9	CAP SCREW(M6x20L)	3	44	BALL BEARING(6002ZZ)	5
10	CLAMPING BOLT(M8)	4	45	CAP SCREW (M6x16L)	6
11	Z-AXIS LEAD SCREW	1	46	LEFT BEARING SEAT SET	1
12	SEAT SET	1	47	WORKING TABLE	1
13	CAP SCREW(M8x16L)	2	48	KEY (4x4x20L)	3
14	BALL BEARING(6002Z)	2	49	LONGIT UDINAL LEAD SCREW	1
15	SPRING PIN(4X40)	1	50	CAP SCREW (M8x20L)	2
16	SEAT RING	1	51	LONGITUDINAL LEAD SCREW NUT	1
17	SCREW NUT SET	1	52	STOPPER SET	2
18	UPPER RUBBER CHIP COVER	1	53	STOPPER BUSH	2
18A	DOWNNER RUBBER CHIP COVER	1	54	CAP SCREW (M6x20L)	2
19	CAP SCREW(M5x12L)	8	55	RIGHT BEARING SEAT SET	1
20	BALL BEARING (6003ZZ)	2	56	SADDLE	1
21	CAP SCREW (M6x20L)	2	57	SAME 10	
22	SEAT SET	1	58	SAME 6	
23	BRACKET	1	59	CAP SCREW(M8x16L)	2
24	WORM WHEEL	1	60	STOPPER BLOCK	1
25	WASHER	1	61	CROSS TRAVEL GIB	1
26	CAP SCREW (M8x14L)	1	62	CROSS LEAD SCREW NUT	1
27	T-SLOT BOLT (1 / 2"x50L)	3	63	WING SCREW (3/8")	2
28	ELETRICAL CONTROL BOX	1	64	LONGITUDINAL TRAVEL GIB	1
29	WORM SHAFT	1	65	CROSS LEAD SCREW	1
30	KEY (3x3x15L)	2	66	FRONT BEARING SEAT SET	1
31	BALL BEARING (6204ZZ)	2	67	MEMORY RING	3
32	BEARING SEAT SET	1	68	HANDLE GRIP(3/8")	3
33	SAME 31		69	CAP SCREW (M8x30L)	1
34	SEAT RING	1	70	CAP SCREW (M8x14L)	3
35	MEMORY RING	1	71	TILTING GRADUATED PLATE	1
36	SET NUT	1	72	RIVET	3
36A	MEMORY RING SET	1			

OPTIONAL ACCESSORIES FOR Z-AXIS UP & DOWN BY GEAR MOTOR

73	GEAR MOTOR(1/4" HP)	1
74	CAP SCREW (M8x20L)	4
75	CAP SCREW (M8x16L)	4
76	BALL BEARING (6005ZZ)	1
77	SPRING PIN(4Øx40L)	1
78	SEAT RING	1
79	SEAT SET(GEAR MOTOR HOUSING)	1