

## STEELMASTER CS250 PARTS BREAKDOWN

CS250/1MOTOR	MOTOR, 1PH T0 SUIT CS250 COLD SAW
CS250/1PSWITCH	SWITCH, 1PH T0 SUIT CS250 COLD SAW
CS250/1PSWITCHBOX	SWITCH BOX, 1PH T0 SUIT CS250 COLD SAW
CS250/1PTRAN	TRANSFORMER, 1PH T0 SUIT CS250 COLD SAW
CS250/20	ACME LEAD SCREW T0 SUIT CS250 COLD SAW
CS250/20A	SPRING FOR VICE LEAD SCREW T0 SUIT CS250 COLD SAW
CS250/315/ONSWITCH-1P	ON OFF SWITCH T/S 240V CS250 & CS315 COLDSAW
CS250/315/ONSWITCH-3P	ON OFF SWITCH T/S 415V CS250 & CS315 COLDSAW
CS250/315/SPEEDSWITCH-1P	SPEED SWITCH T/S 240V CS250 & CS315 COLDSAW
CS250/315/SPEEDSWITCH-3P	SPEED SWITCH T/S 415V CS250 & CS315 COLDSAW
CS250/315-MICROSWITCH	MICRO SWITCH, T0 SUIT ALL CS COLD SAWS
CS250/315SWITCH	TRIGGER SWITCH T/S CS250/315 COLD SAW
CS250/33	TANK FILTER T0 SUIT CS250 COLD SAW
CS250/3MOTOR	MOTOR, 3PH T0 SUIT CS250 COLD SAW
CS250/3PSWITCH	SWITCH, 3PH T0 SUIT CS250 COLD SAW
CS250/3PSWITCHBOX	SWITCH BOX, 3PH T0 SUIT CS250 COLD SAW
CS250/3PTRAN	TRANSFORMER, 3PH T0 SUIT CS250 COLD SAW
CS250/42	HEAD LEVER HANDGRIP T/S CS250 COLD SAW
CS250/45	SPINDLE T0 SUIT CS250 COLD SAW
CS250/47/48	FLANGE T0 SUIT CS250 COLD SAW
CS250/49	FLANGE BOLT T0 SUIT CS250 COLD SAW
CS250/5	LEVER T0 SUIT CS250 COLD SAW
CS250/50	CAST GUARD T0 SUIT CS250 COLD SAW
CS250/53	PLASTIC GUARD T0 SUIT CS250 COLD SAW
CS250/63	WORM GEAR T0 SUIT CS250 COLD SAW
CS250/79	RETURN SPRING T0 SUIT CS250 COLD SAW
CS250/88	PUMP CONNECTOR BOX T/S CS250 COLD SAW
CS250/90	COOLANT PUMP T0 SUIT CS250 COLD SAW
CS250/93	WORM SCREW T0 SUIT CS250 COLD SAW
CS250/CABLELUG	CABLE LUG T/S CS250 COLD SAW
CS250/CORD	CONTROL CORD T0 SUIT CS250 COLD SAW
CS250/COWL	MOTOR COWL T0 SUIT CS250 COLD SAW
CS250/ENDCAP	END CAP T0 SUIT CS250 COLD SAW
CS250/FLANGEPIN	FLANGEPIN T0 SUIT CS250 COLD SAW
CS250-1	250MM 1PH 1 SPEED COLD SAW
CS250-3	250MM 3PH 2 SPEED COLD SAW
CS250STAND	STAND FOR 250MM STEELMASTER COLD SAW

