

STEELMASTER CS315 PARTS BREAKDOWN

| | |
|-------------------|---|
| CS315/01 | BASE T0 SUIT CS315 COLD SAW |
| CS315/10 | VICE PLATE T0 SUIT CS315 COLD SAW |
| CS315/101 | GEAR T0 SUIT CS315 COLD SAW |
| CS315/125 | PUMP CONNECTION BOX T/S CS315 COLD SAW |
| CS315/128 | COOLANT PUMP T0 SUIT CS315 COLD SAW |
| CS315/17 | VICE BODY T0 SUIT CS315 COLD SAW |
| CS315/18 | VICE BACK JAW T0 SUIT CS315 COLD SAW |
| CS315/1MOTOR | MOTOR, 1PH T0 SUIT CS315 COLD SAW |
| CS315/1PSWITCHBOX | SWITCHBOX, 1PH T0 SUIT CS315 COLD SAW |
| CS315/1PTRAN | TRANSFORMER, 1PH T0 SUIT CS315 COLD SAW |
| CS315/2 | BOTTOM REVOLVING PLATE T/S CS315 COLDSAW |
| CS315/25 | VICE HANDLE T0 SUIT CS315 COLD SAW |
| CS315/35 | THREADED VICE SHAFT T/S CS315 COLD SAW |
| CS315/3MOTOR | MOTOR, 3PH T0 SUIT CS315 COLD SAW |
| CS315/3PCONTACTOR | CONTACTOR, 3PH T0 SUIT CS315 COLD SAW |
| CS315/3PRELAY | RELAY, 3PH T0 SUIT CS315 COLD SAW |
| CS315/3PSWITCHBOX | SWITCHBOX, 3PH T0 SUIT CS315 COLD SAW |
| CS315/3PTRAN | TRANSFORMER, 3PH T0 SUIT CS315 COLD SAW |
| CS315/3SLOWMOTOR | MOTOR, 3PH T0 SUIT CS315-SLOW COLD SAW |
| CS315/41 | TANK FILTER T0 SUIT CS315 COLD SAW |
| CS315/5 | LEVER T0 SUIT CS315 COLD SAW |
| CS315/59 | RETURN SPRING T0 SUIT CS315 COLD SAW |
| CS315/62 | GEARBOX HOUSING T/S CS315 COLD SAW |
| CS315/7 | VICE TABLE T0 SUIT CS315 COLD SAW |
| CS315/72-74 | CONTROL HANDLE T/S CS315 COLD SAW |
| CS315/75 | LOCK NUT T0 SUIT CS315 COLD SAW |
| CS315/76 | WORM GEAR T0 SUIT CS315 COLD SAW |
| CS315/78 | SPINDLE T0 SUIT CS315 COLD SAW |
| CS315/81 | FLANGE T0 SUIT CS315 COLD SAW |
| CS315/82 | SCREW T0 SUIT CS315 COLD SAW |
| CS315/86 | BLADE COOLANT ADAPTOR T/S CS315 COLD SAW |
| CS315/89 | BLADE GUARD, PLASTIC T0 SUIT CS315 COLD SAW |
| CS315/9 | VICE PLATE T0 SUIT CS315 COLD SAW |
| CS315/CORD | CONTROL CORD T0 SUIT CS315 COLD SAW |
| CS315/COWL | MOTOR COWL T0 SUIT CS315 COLD SAW |
| CS315/FLANGEPIN | FLANGEPIN T0 SUIT CS315 COLD SAW |
| CS315/GUARD | GUARD T0 SUIT CS315 COLD SAW |
| CS315-1 | 315MM 1PH 1 SPEED 42 RPM COLD SAW |
| CS315-3 | 315MM 3PH 2 SPEED 42/84 RPM COLD SAW |
| CS315-3SLOW | 315MM 3PH 2 SPEED 21/42 RPM COLD SAW |
| CS315-3SLOWDEMO | DEMO MODEL - 315MM 3PH 2 SPEED 21/42 RPM COLD SAW |
| CS315STAND | STAND FOR 315MM STEELMASTER COLD SAW |

