

Industrial Drilling Machines - Belt Drive

K&K INDUSTRIAL

QUALITY TAIWANESE MACHINES WITH HEAVY DUTY CASTING AND CONSTRUCTION FOR PROVEN LASTING DURABILITY IN INDUSTRIAL WORKSHOPS

Extra Heavy Duty Industrial Drilling Machine Range

ALL KK INDUSTRIAL DRILLS COME COMPLETE WITH DRILL CHUCK, ARBOR & DRILL DRIFT

Bench Drill Press



Part Number	K1418	K1720HD
Description	Bench Drill	Bench Drill
Motor	550W TEFC 240V	750W TEFC 240V
Capacity	23mm (7/8")	23mm (7/8")
Chuck	16mm (5/8")	16mm (5/8")
Spindle Taper	No2 Morse Taper	No2 Morse Taper
Max. Spindle Stroke	85mm	85mm
Spindle to Column	165mm	215mm
Swing	365 (14")	430 (17")
Speed (R.P.M)	16 Speed 180 - 2700rpm	12 Speed 290 - 2330rpm
Column Diameter	80mm	80mm
Max. Spindle To Table	470mm	460mm
Max Spindle To Base	650mm	638mm
Overall Height	1010mm	1010mm
Table Size	350mm Dia.	350mm Dia.
Base Size	458 x 265mm	505 x 278mm
Weight	60kg	72kg

Pedestal Drill Press



Part Number	K1418F	K1720HFD	K2532	K2532-3PH
Description	Pedestal Drill	Pedestal Drill	Maxi Drill	
Motor	550W TEFC 240V	750W TEFC 240V	1200W 240V	1500W 415V
Capacity	23mm (7/8")	23mm (7/8")	32mm (1 1/4")	
Chuck	16mm (5/8")	16mm (5/8")	16mm (5/8")	
Spindle Taper	No2 Morse Taper	No2 Morse Taper	No3 Morse Taper	
Max. Spindle Stroke	85mm	85mm	122mm	
Spindle to Column	165mm	215mm	280mm	
Swing	365 (14")	430 (17")	560 (22")	
Speed (R.P.M)	16 Speed 180 - 2700rpm	12 Speed 290 - 2330rpm	12 Speed 145 - 2530rpm	
Column Diameter	80mm	80mm	92mm	
Max. Spindle To Table	700mm	775mm	710mm	
Max Spindle To Base	1220mm	1270mm	1230mm	
Overall Height	1600mm	1600mm	1752mm	
Table Size	350mm Dia.	350mm Dia.	473 x 410mm	
Base Size	458 x 265mm	495 x 280mm	575 x 500mm	
Weight	70kg	78kg	158kg	

Drill Chucks



DCK12305-2



DC11305-2

Part Number	Description
DC11506-3	13m Drill Chuck, 3/8" - 24 Thread Mount
DC11506-1	13m Drill Chuck, 1/2" - 20 Thread Mount
DC11305-2	16m Drill Chuck, J3 Mount
DCK12305-2	16m Keyless Drill Chuck, J3 Mount
DC11306-1	19m Drill Chuck, J3 Mount

Arbors



Part Number	Description
7002-3	Drill Chuck Arbor #2 Morse Taper - #3 Jacobs Taper
7002-6	Drill Chuck Arbor #2 Morse Taper - #6 Jacobs Taper
7003-3	Drill Chuck Arbor #3 Morse Taper - #3 Jacobs Taper
7003-6	Drill Chuck Arbor #3 Morse Taper - #6 Jacobs Taper
7004-3	Drill Chuck Arbor #4 Morse Taper - #3 Jacobs Taper
7004-6	Drill Chuck Arbor #4 Morse Taper - #6 Jacobs Taper